

Dolan Chemical Laboratory 4001 Bixby Road Groveport, OH 43125 T: 614-836-4221, Audinet 210-4221 F: 614-836-4168, Audinet 210-4168 http://aepenv/labs

Water Analysis

Location: Mountaineer Plant Report Date: 5/1/2013

| 1 | st | S | ta | α | e | F | e | e | d | |
|---|----|---|----|---|---|---|---|---|---|--|
| | | | | | | | | | | |

| Sample Number: | 131611-001 | D | ate Collected: | 04/24/2013 | 3 08:00 | Date Received: 4/2 | 24/2013 |
|----------------|------------|----------|----------------|------------|-------------|--------------------|-----------|
| Parameter | | Result U | nits RL | MDL | Analysis By | Analysis Date/Time | Method |
| Selenium, Se | | 270 ug | g/L 0.50 | 0.20 | DPC | 04/29/2013 11:45 | EPA 200.8 |

2nd Stage Feed

| Sample Number: | 131611-002 | | Date Co | llected: | 04/24/2013 | 3 08:00 | Date Received: 4/2 | 24/2013 |
|----------------|------------|--------|---------|----------|------------|-------------|--------------------|-----------|
| Parameter | | Result | Units | RL | MDL | Analysis By | Analysis Date/Time | Method |
| Selenium, Se | | 2.9 | ug/L | 0.50 | 0.20 | DPC | 04/29/2013 11:49 | EPA 200.8 |

Bioreactor Effluent

| Sample Number: | 131611-003 | | Date Co | llected: | 04/24/2013 | 08:00 | Date Received: 4/2 | 24/2013 |
|----------------|------------|--------|---------|----------|------------|-------------|--------------------|-----------|
| Parameter | | Result | Units | RL | MDL | Analysis By | Analysis Date/Time | Method |
| Selenium, Se | | 1.5 | ug/L | 0.50 | 0.20 | DPC | 04/29/2013 11:54 | EPA 200.8 |

Brian Snyder, Chemist II

Email bssnyder@aep.com Tel. 614-836-4224

Fax 614-836-4168 Audinet 210-4224

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.

Mountaineer Plant, 131611 Page 1 of 1